

FIG. 1




FIG. 2




FIG. 3






FIG. 4



DIRECTION OF TURN AT A REDUCTION  
OF THE FLOW SECTION OF THE SUPPLY  
CHANNEL OF THE COMPRESSION VALVE



DIRECTION OF TURN AT A REDUCTION  
OF THE FLOW SECTION OF THE SUPPLY  
CHANNEL OF THE EXPANSION VALVE

FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16



09/744,003 - U 013214-0  
Replacement Sheet(s)




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23



09/744,003 - U 013214-0  
Replacement Sheet(s)






FIG. 24



t (s)

FIG. 25







FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32




FIG. 33



09/744,003 - U 013214-0  
Replacement Sheet(s)




FIG. 34





FIG. 35




FIG. 36